



Two, three and four-vat Frymaster McDonald's BIGLA-T fryers have two ports for gas connection. Out of the box, they should both be capped.

Inspect a new fryer to ensure both are capped.

Remove the cap best suited to the installation and ensure the unused port remains capped.