

(This bulletin and all other active bulletins are downloadable from our website at www frymaster com/parts, service.)

(This bulletin and all other active bulletins are downloadable from our website at www.irymaster.com/parts_service.)		
Bulletin 2004-41-ABDE	Page 1 of 1	Date: 12/17/2004
SUBJECT: UHC-P Displays		
There have been some failur beeping during startup. The prol assembly of some of the display	blem has been traced to co	ne UHC-P. The cabinets fail to stop ntaminated flux used during the
Please pull your existing sto \$240 list). These displays should		UHC-Ps (part number 807-3707, C-P cabinet is down.
Place a stocking order for ne the new displays are delivered.	ew displays, returning the o	original stock to Frymaster when