



# Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at <http://www.frymaster.com/iframe.asp?oc=fry&region=default&article=onlineliterature.xml>.)

Bulletin 2008-05-ABDE

Page 1 of 1

Date: 04/24/2008

## SUBJECT: Recall of Durakool Mercury Contactors

**This bulletin cancels and replaces Service Bulletin 2008-04-ABDE. Remove bulletin 2008-04-ABDE from your active files.**

Effective immediately, Durakool mercury contactors, part number 807-1071, with digits 9-5, 9-6 or 9-7 in the first two positions of the date code range (see example below) and 9-1 in the last two positions should be removed from stock and isolated. Reorder an equal number of 807-2284, a mechanical contactor, which can be substituted for the Durakool unit.

Orders placed for 807-1071 contactors have been filled with 807-2284 since April 17<sup>th</sup>.

Isolate and hold the Durakool contactors in the affected date range. Do not immediately return them to Frymaster. Do not remove recently installed Durakool contactors from properly operating fryers.

If you haven't provided a count of your 807-1071 contactors in the affected date range, please email that number to [esutton@frymaster.com](mailto:esutton@frymaster.com).



Contactors with a 9-5, 9-6 or 9-7 in the first two positions and a 9-1 in the last two should be isolated.

Frymaster L.L.C., 8700 Line Avenue, P.O. Box 51000, Shreveport, LA 71135-1000

Shipping Address: 8700 Line Avenue, Shreveport, LA ZIP 71106

TEL 318-865-1711

FAX 318-219-7135

24-Hour SERVICE HOTLINE 800-551-8633

WebSite - <http://www.frymaster.com/general.asp?article=servicehome.xml>

E-mail - [service@frymaster.com](mailto:service@frymaster.com)