

## Service Bulletin

**This service bulletin replaces earlier versions of this bulletin with revised links.**

**Subject: Touch Screen Fryer Software Updates**

**Models: Touch Screen Fryers**

**8/30/2023**

Software updates on Frymaster Touch Screen Fryers may require some additional steps to successfully update the fryer.

This typically occurs when a controller, with a newer version of software, is installed on a fryer with controllers, that have an older version software. To ensure proper functionality, the software **MUST** be updated when the software versions **DO NOT MATCH**. Failure to follow these instructions can result in **CAN COMMUNICATION ERRORS** and failed software updates.

The instructions are at the following links below.

[Burger King FQ4000 Software Update Instructions](#)

[General Market FQ4000 Software Update Instructions](#)

[McDonalds M4000 Software Update Instructions for \*\*ALL AREAS EXCEPT Japan and Korea!!\*\*](#)

[McDonalds M4000 Software Update Instructions for \*\*JAPAN ONLY!!\*\*](#)

[McDonalds M4000 Software Update Instructions for \*\*KOREA ONLY!!\*\*](#)

[Popeye's FQ4000 Software Update Instructions](#)

[7-Eleven FQ4000 Software Update Instructions](#)

[Taco Bell FQ4000 Software Update Instructions](#)

