

# FLUE ANGLE MODIFICATION INSTRUCTIONS FOR FRYPOTS BUILT BEFORE AUGUST 1994

(FRYPOTS WITH A FLUE ANGLE THAT RUNS THE FULL WIDTH OF THE FRYPOT)

[Used with H50 Series Service Flue Assemblies 806-5859SP and 806-5860SP]

The flue angle on H50 Series frypots manufactured before August 1994 runs the full width of the frypot. A 4.00 inch notch (see illustration) must be cut in the angle to allow installation of replacement flue assemblies 806-5859SP and 806-5860SP.

