# Frymaster ODC35 (Oil Disposal Caddy)



#### CAUTION:

- To minimize the chances for burns, always allow the oil to cool below 100°F (38°C) before draining or transporting to the disposal area.
- Always use PPE (safety gloves and splash shields) when using the ODC35.
- Do **NOT** fill above marked fill line. •
- Do **NOT** move without the lid securely clasped and the gasket in place.

8197450

and empty the ODC35 into

the disposal vessel.

### Cleaning

Clean the exterior surfaces of the ODC35 with a soft cloth and a solution of detergent and water. It is not necessary to clean the interior of the reservoir, but if desired it may be wiped down with clean paper towels to remove excess residual shortening.

# Service, Parts Ordering

A list of Frymaster Factory Authorized Servicers (FAS's) is located on the Frymaster website at http://www.frymaster.com/service

Refer to this list to find the agency nearest you. If you do not have access to this list, contact the Frymaster Technical Service Department at 1-800-551-8633 or 1-318-865-1711or by e-mail: fryservice@ welbilt.com.

## **Equipment Damaged in Shipment?**

1. File a claim for damages immediately, regardless of the extent of damages.

2. Inspect for and record all damage and ensure that this information is noted on the freight bill or express receipt and is signed by the person making the delivery.

3. Concealed loss or damage that was unnoticed until the equipment was unpacked should be recorded and reported to the freight company or carrier immediately upon discovery. A concealed damage claim must be submitted within 15 days of the date of delivery. Ensure that the shipping container is retained for inspection.

FRYMASTER DOES NOT ASSUME RESPONSIBILITY FOR DAMAGE OR LOSS INCURRED IN TRANSIT.

