



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at www.frymaster.com/service.)

Bulletin 2002-28-ABD


Page 1 of 1

Date: 12/23/2002

SUBJECT: New Honeywell Pilot & Thermopile Assembly in 35 Series Fryers

Effective 19 December 2002 a new Honeywell pilot and thermopile assembly is being used on Non-CE 35 Series gas fryers.

The new assembly, illustrated below, mounts to the burner manifold in the same way as the previous assembly, but the components of the new assembly (pilot and thermopile) are not interchangeable with those of the old assembly. List prices for the new parts are: pilot - \$26.00, thermopile - \$22.00, complete assembly with mounting bracket - \$81.00. The components of the old assembly remain available for service.



Frymaster L.L.C., 8700 Line Avenue, P.O. Box 51000, Shreveport, LA 71135-1000

Shipping Address: 8700 Line Avenue, Shreveport, LA ZIP 71106

TEL 318-865-1711

FAX 318-219-7135

24-Hour SERVICE HOTLINE 800-551-8633

WebSite - <http://www.frymaster.com/service>

E-mail - service@frymaster.com