



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at www.frymaster.com/parts_service.htm.)

Bulletin 2005-05-ABDE**Page 1 of 1****Date: 04/26/2005**


SUBJECT: Thermocouple Butterfly Adapter

Effective April 1, 2005, the high-limit service kit (P/N 826-1177) no longer includes a blue butterfly thermocouple adapter (P/N 807-0280) used in older MJ35, MJ45, and MJCF gas fryers. All production units previously using the blue adapter will now be manufactured with a metal butterfly adapter.


The metal butterfly adapter (P/N 807-4134) can be purchased as a replacement part, list price US \$12.00. It screws directly into the gas valve at the same location as the previous adapter and the high-limit wires attach directly to the adapter via the provided ¼" spade connectors. When wiring, polarity does not matter.

The metal adapter is much more reliable and durable than the previous adapter and should last the life of the equipment regardless of how many times other components are replaced. It can be used on any Robertshaw gas valve or high-limit applications, which use the older blue adapter.

For more information, call the Frymaster Service Hotline at 1-800-551-8633.



New Metal Butterfly Adapter



Previous Blue Butterfly Adapter