



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at www.frymaster.com/parts_service.)

Bulletin 2005-06-ABDE

Page 1 of 1

Date: 05/11/2005

SUBJECT: HLZ Relay Kits

This bulletin supercedes Service Bulletin 2004-35-ABDE, which is no longer active. Remove 2004-35-ABDE from your active file.

A service kit, 826-2038, is available for the Heated Landing Zone or HLZ. The kit, \$112 list, replaces the 18-amp solid-state relay for the air heater with a 50-amp relay. The new relay is physically larger and requires a different bracket, which is included in the kit.

The 50-amp relay replaced the 18-amp relay in production HLZs in mid-October of 2004. The original 18-amp air-heater relay kit (826-1733) is still available, \$48 list.