



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at <http://www.frymaster.com/iframe.asp?oc=fry®ion=default&article=onlineliterature.xml>.)


Bulletin 2006-20-ABDE

Page 1 of 1

Date: 10/17/2006

SUBJECT: New Spark Module

A new service spark module, 807-4383, is beginning to ship in a kit, 826-2117 (\$133 list), which includes new spark cable adapters, a resistor and instructions. The module is a replacement for a Robertshaw model, 807-3563, and an earlier Honeywell model, 807-4037. The function is the same. The new module will require the addition of a 1/4" female push-on terminal on the existing ground wire, replacing the existing eyelet. An annotated view of the new module is shown below. When installing the module on a fryer equipped with an older Thermatron board, identified by a large yellow transformer, a provided resistor has to be connected to the melt cycle disable connections, which extends the melt cycle ON time. This is necessary because the new module has a 4.5 second delay when power is applied.



Frymaster L.L.C., 8700 Line Avenue, P.O. Box 51000, Shreveport, LA 71135-1000

Shipping Address: 8700 Line Avenue, Shreveport, LA ZIP 71106

TEL 318-865-1711

FAX 318-219-7135

24-Hour SERVICE HOTLINE 800-551-8633

WebSite - <http://www.frymaster.com/general.asp?article=servicehome.xml>

E-mail - service@frymaster.com