



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at <http://www.frymaster.com/iframe.asp?oc=fry®ion=default&article=onlineliterature.xml>.)

Bulletin 2007-14-ABDE

Page 1 of 1

Date: 5/14/2007

SUBJECT: UHC-P Displays

When ordering UHC-P displays, part number 807-4201, Frymaster may ship part number 807-3707, an identical part. The price is the same for both displays, \$240.00 list.

The 807-4201 part number can continue to be ordered and it will remain an active part number. Orders for the 807-4201 part will be filled by that number or the 807-3707 number until the stock of the 807-3707 display is exhausted. Both numbers will be active in our system and should be active in the inventory systems of our service network.

If you have questions, call 800-551-8633.