Frymaster Dean Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at http://www.frymaster.com/iframe.asp?oc=fry®ion=default&article=onlineliterature.xml.)

Bulletin 2010-7-ABDE

Page 1 of 1

Date: 7/7/2010

SUBJECT: Membrane Replacement Kit for UHC-P

A kit is now available to replace the display membrane in a UHC-P cabinet. The kit, 826-2749 (\$137 list), eliminates the need to replace a bezel assembly when repairing a worn membrane. The kit includes the membrane and its ribbon cable attached to a metal assembly (see below). The circuit board must be removed from the original membrane and attached to the replacement assembly. The cabinet will require re-addressing and reprogramming. The kit instructions, 819-6637, are posted on the Service Literature page at Frymaster.com.



Figure 1: The kit includes a metal assembly-mounted membrane, which eliminates the need to replace a cabinet bezel to repair a worn or malfunctioning membrane.