



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at <http://www.frymaster.com/iframe.asp?oc=fry®ion=default&article=onlineliterature.xml>.)

Bulletin 2010-15-ABDE

Page 1 of 1

Date: 12/16/2010

SUBJECT: UHC-HD Boards

The master control and master display circuit boards for the UHC-HD have been changed, beginning with serial number 1010UH0920. All cabinets built in November and later have the new boards.

The new boards, due to firmware changes, are not compatible with boards in earlier cabinets. Earlier boards in your parts inventory should be returned to Frymaster and new boards ordered to replace them. ASA's outside of the US should ship boards to their Frymaster Regional Managers for scrapping.

The new service boards are a direct replacement part for boards in cabinets built in November or later.

The new boards cannot be comingled with the older boards. See the matrix below for guidance in replacing master control and master display boards in UHC-HD cabinets.



The part number tag on an original master control board is shown above in an inset. The tag on the master display board is shown below.

Original Master Display Board	Original Master Control Board	If Present
807-4872	807-4862	Both must be replaced with new boards.
New Master Display Board	New Master Control Board	If Present
807-5156	807-5150	Replace only the failed board with direct replacement board.

