

Service Bulletin

Subject: Discontinue Software Updates at Startup

Models: All Frymaster Touch Screen Fryers

5/15/2023

This bulletin replaces and rescinds service bulletin SB20-10.

Effective immediately **DISCONTINUE** any software updates during startup on **ALL TOUCH SCREEN FRYERS**. The fryers ship with the correct software, so a software update is **NOT** necessary unless a service part is replaced.