

## Service Bulletin

800-551-8633  
318-865-1711

[WWW.FRYMASTER.COM](http://WWW.FRYMASTER.COM)  
EMAIL: [FRYSERVICE@WELBILT.COM](mailto:FRYSERVICE@WELBILT.COM)

**This bulletin addresses Taco Bell Gas Fryer Revised Kit Update Instructions**

**Subject: Taco Bell Touch Fryer Kit Updates**

**Models Affected: Taco Bell FilterQuick Touch Gas Fryers (FQG30-T)**

**7/1/2024**

This is **ONLY** applicable to those companies that are updating the Taco Bell Touch fryer kits. If you haven't performed the update on Taco Bell gas fryers with the new software version 174 kits, download the updated instructions at the link below that have some additional troubleshooting instructions.

[819-8040](#)

[Taco Bell FQG30-T Fryer OIB Plug Inspection, SW Update, Rack Swap](#)