

## Service Bulletin

This addresses the **obsolete** gray actuator for 4000 series touch screen fryers.


**Subject: Obsolete Gray Square Rotary Actuators**

**Models: 4000 Series Touch Screen Fryers**

**7/8/2025**

**GRAY** square rotary actuators (PN **130013720**) that were used on Frymaster 4000 series Touch Screen fryers are obsolete (see Figures 1 & 2). When replacing the gray actuator, it will need to be replaced with the **BLUE** (PN 8075809) or **BLACK** (PN 8075808) rotary actuators (see Figure 3).


Reference the associated parts manuals to identify which actuator (blue or black) will need to be used to replace the gray actuator, as these are location specific.



**Figure 1**



**Figure 3**



**Figure 2 Obsolete Gray Square Actuator attached to drain valve**