

Service Bulletin

800-551-8633

318-865-1711

WWW.FRYMASTER.COM

EMAIL: FRYSERVICE@FRYMASTER.COM

Subject: Loctite® 567 6ML Discontinued

8/19/2025

Due to shipping restrictions, Loctite® 567 thread sealant will no longer be included in service kits. Ensure that technicians carry Loctite® 567 thread sealant or a comparable thread sealant when performing service on Frymaster equipment.

