

Service Bulletin

This bulletin addresses UHCTHD mounting point repairs to units with serials starting with 2509. The mounting rivet nuts may have loosened.

Subject: UHCTHD Mounting Point Repair
Models: McDonald's UHCTHD Touch Screen Holding Cabinets

01.23.2026

For affected UHCTHD units with serials starting with 2509 currently released for international market.

The following parts do not have a part number and will need to be sourced locally.

Qty - 4 304 stainless steel M6 rivet nut (Outer diameter 0.34 in / 8.9mm)

Qty - 4 M6 x 20 head bolt

Install a **304 stainless steel M6 rivet nut (outer diameter 0.34 in / 8.9 mm)** from the underside.

Using a **90-degree angled rivet-nut installation tool** will allow the repair to be completed with the UHCTHD remaining in place

After installation, replace the original hardware with an M6 x 20 mm hex-head bolt.

Frymaster will cover labor and cost of parts to repair.

