



# Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at [www.frymaster.com/service](http://www.frymaster.com/service).)

**Bulletin 2003-07-AB**

**Page 1 of 1**

**Date: 01/16/2003**

## **SUBJECT: TCF Replacement Frypots**

**This bulletin cancels and replaces Service Bulletin AB-13-98. Remove bulletin AB-13-98 from your active files.**

Order frypot P/N 823-1944 when replacing any TCF frypot.

Additionally, for units manufactured before 18 October 1993 (9310XX series AF and earlier), an additional kit is required. Order P/N 826-1159 for natural gas units or P/N 826-1160 for Propane (LP) units. If the frypot being replaced is under warranty, include the kit in the warranty claim.