



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at <http://www.frymaster.com/general.asp?article=servicehome.xml>.)

Bulletin 2006-13-ABDE**Page 1 of 1****Date: 08/18/06**

SUBJECT: Performance Pro and Master Jet Target Replacement

Effective August 2006, ceramic deflectors and the brackets that hold them will be replaced with one-piece metal deflectors for Performance Pro and Master Jet fryers. This is a direct replacement. If the ceramic target and bracket are ordered, you will receive a one-piece metal target. Ceramic targets (without brackets) will be available until supplies are exhausted. Ceramic and metal targets can be intermingled in the same fryer.


230-1177 replaces 806-0225 (45 & CF, side)

230-1206 replaces 806-3606 (45, rear)


230-1178 replaces 806-4720 (35, side)

230-1180 replaces 806-3605 (35 & CF, rear)

230-1568 **MUST** be used on all J1Cs and MJ15s for proper operation and light-offs.



Ceramic Deflectors



Metal Deflectors

Frymaster L.L.C., 8700 Line Avenue, P.O. Box 51000, Shreveport, LA 71135-1000

Shipping Address: 8700 Line Avenue, Shreveport, LA ZIP 71106

TEL 318-865-1711

FAX 318-219-7135

24-Hour SERVICE HOTLINE 800-551-8633

Website - <http://www.frymaster.com>

E-mail - service@frymaster.com