



# Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at <http://www.frymaster.com/iframe.asp?oc=fry&region=default&article=onlineliterature.xml>.)

Bulletin 2006-21-ABDE


Page 1 of 1

Date: 10/17/2006

## SUBJECT: SMT Service Interface Board Kits

In October, Frymaster and Dean began shipping Surface Mount Technology (SMT) interface boards for selected models in service orders. The first service boards to ship are for the H50/55-series fryer. Instructions are available online: 819-6237; the kit number is 826-2264 (\$152 list). Other service boards will be converted to surface mount in the coming months. Surface mount boards and computers went into production fryers in August 2006. See Service Bulletin 2006-19.

In all cases, the old board's part number will roll to a kit, which will include harnesses for installation of the new board. Harnesses are required to connect the sound device on all boards and spark modules on gas boards. Gas boards will include instructions with color-coded wiring placement guides. Electric boards will include an adapter for the sound device. The new boards are distinguished from the old by the microamp plugs in place of spade terminals. The red LED's have also been replaced by smaller green LED's, embedded in small white cubes.



Frymaster will ship the original interface boards and computers on service orders until supplies are exhausted.

**Figure 1:** The new H55 service board kit (826-2264) ships with harnesses, which attach the board to the spark module and the sound device.

Frymaster L.L.C., 8700 Line Avenue, P.O. Box 51000, Shreveport, LA 71135-1000

Shipping Address: 8700 Line Avenue, Shreveport, LA ZIP 71106

TEL 318-865-1711

FAX 318-219-7135

24-Hour SERVICE HOTLINE 800-551-8633

WebSite - <http://www.frymaster.com/general.asp?article=servicehome.xml>

E-mail - [service@frymaster.com](mailto:service@frymaster.com)