

Service Bulletin

Subject: FilterQuick Fryer Rollout
10/22/2019

The rollout continues, nationally and internationally, for Frymaster's touchscreen-equipped fryer. The FilterQuick Touch, which initially went into Taco Bell stores in large numbers, is now approved by McDonald's, Burger King, Arby's and is being tested, in gas and electric models, in other chains.

The unique parts for this new platform are listed below. These parts should be stocked in sufficient quantities to support the growing use of this fryer.



Platform	Gas	Elec	Part #	Description
Burger King	x	x	1087515SP	Controller, FQ4000
Taco Bell	x	x	1087847SP	Controller, FQ4000
	x	x	1087535SP	Board, FIB w/ Software
Arby's	x	x	1087769SP	Controller, FQ4000
McDonald's	x	x	1086730SP	Controller, M4000 Domestic USA
	x	x	1088437SP	Controller, M4000 International CE
	x	x	1086726SP	Controller, M4000 Japan
	x	x	1088467SP	Controller, M4000 Israel
	x	x	1086575	Board, FIB w/ Software
Shared Components	x	x	1085979	SIB (Smart Interface Board)
	x	x	1087513SP	Board, FIB w/ Software (outside chain-specific models noted above)
	x	x	1085996SP	VIB Board Assembly
	x	x	8075855	Power Supply, 24VDC, 130W ATO, Actuators, Filter Pump, Top Off Pump
	x	x	8075632	Terminator, CAN End Communication RJ11
	x	x	8075974	Power Supply, 24VDC, 15W for KCCM SUI board
	x		8075949	Module, Ignition Single Spark, Fenwal
	x		8076382	Module, Ignition Single Spark Fenwal FV (Left) / DV Australia 3 sec
	x		8076383	Module, Ignition Single Spark Fenwal FV (Right) Australia 4 sec
	x		8075623	Relay, 24VDC SPDT OIB (Oil Is Back) Sensor
	x		8074812	Relay Board, 7-second Time Delay, 120V

	x		8074934	Relay Board, 7-second Time Delay 220V, 230V, 240V and 250V units
	x		8075731	Relay Board, 7-second Time Delay 100V
	x		8075730	Sensor Assy, Oil 100V Japan
	x		8076384	Sensor Assy, Oil 120V
	x		8076385	Sensor Assy, Oil 220V International
	x		8076386	Sensor Assy, Oil 230V International
	x		8076387	Sensor Assy, Oil 240V/250V International
	x	x	8263288	O-Rings