

Service Bulletin

This bulletin addresses the re-introduction of a dual spark ignition module for **Non-CE** FPPH55 full vat fryers.

Subject: Fenwal Dual Spark Ignition Module

Models: Non-CE FPPH55 Full Vat Fryers

5/7/2026

Beginning in February 2024, Frymaster reintroduced dual spark ignition modules for **NON-CE H55 FULL VAT FRYERS ONLY**. This allows a single dual spark module to operate both sides of the H55 full vat fryer.

This new single Fenwal dual spark module, eliminates the need for two single spark modules for Non-CE H55 full vat fryers, manufactured with serial numbers beginning 2402 and later.

The part number for the new dual spark module is PN 130208190. The ignition harness for this module is PN 8076651. Please order sufficient stock to support any H55 full vat fryers in your area.

This dual spark module **DOES NOT** replace single spark modules currently installed on fryers in the field. It should **ONLY** replace existing failed dual spark modules, installed in full vat H55 fryers manufactured with serials beginning 2402 and later, which have the dual spark module installed.




Figure 1